

MS 2 1200	H-RO MO 2, H-P MO 202, H-SHK MO R 2, H-T M 1200	MS 3 1200	H-RO MO 3, H-P MO 202, H-SHK MO R 3, H-T M 1200
MS 2 1400	H-RO MO 2, H-P MO 202, H-SHK MO R 2, H-T M 1400	MS 3 1400	H-RO MO 3, H-P MO 202, H-SHK MO R 3, H-T M 1400
MS 2 1600	H-RO MO 2, H-P MO 202, H-SHK MO R 2, H-T M 1600	MS 3 1600	H-RO MO 3, H-P MO 202, H-SHK MO R 3, H-T M 1600
MS 2 1800	H-RO MO 2, H-P MO 202, H-SHK MO R 2, H-T M 1800	MS 3 1800	H-RO MO 3, H-P MO 202, H-SHK MO R 3, H-T M 1800
MS 2M 1200	H-RO MO 2M, H-P MO 202, H-SHK MO R 2, H-T M 1200	MS 3M 1200	H-RO MO 3M, H-P MO 202, H-SHK MO R 3, H-T M 1200
MS 2M 1400	H-RO MO 2M, H-P MO 202, H-SHK MO R 2, H-T M 1400	MS 3M 1400	H-RO MO 3M, H-P MO 202, H-SHK MO R 3, H-T M 1400
MS 2M 1600	H-RO MO 2M, H-P MO 202, H-SHK MO R 2, H-T M 1600	MS 3M 1600	H-RO MO 3M, H-P MO 202, H-SHK MO R 3, H-T M 1600
MS 2M 1800	H-RO MO 2M, H-P MO 202, H-SHK MO R 2, H-T M 1800	MS 3M 1800	H-RO MO 3M, H-P MO 202, H-SHK MO R 3, H-T M 1800
MSE 2 1200	H-RO MO 2, H-P MO 202, H-SHK MO R 2, H-T ME 1200	MSE 3 1200	H-RO MO 3, H-P MO 202, H-SHK MO R 3, H-T ME 1200
MSE 2 1400	H-RO MO 2, H-P MO 202, H-SHK MO R 2, H-T ME 1400	MSE 3 1400	H-RO MO 3, H-P MO 202, H-SHK MO R 3, H-T ME 1400
MSE 2 1600	H-RO MO 2, H-P MO 202, H-SHK MO R 2, H-T ME 1600	MSE 3 1600	H-RO MO 3, H-P MO 202, H-SHK MO R 3, H-T ME 1600
MSE 2 1800	H-RO MO 2, H-P MO 202, H-SHK MO R 2, H-T ME 1800	MSE 3 1800	H-RO MO 3, H-P MO 202, H-SHK MO R 3, H-T ME 1800
MSE 2M 1200	H-RO MO 2M, H-P MO 202, H-SHK MO R 2, H-T ME 1200	MSE 3M 1200	H-RO MO 3M, H-P MO 202, H-SHK MO R 3, H-T ME 1200
MSE 2M 1400	H-RO MO 2M, H-P MO 202, H-SHK MO R 2, H-T ME 1400	MSE 3M 1400	H-RO MO 3M, H-P MO 202, H-SHK MO R 3, H-T ME 1400
MSE 2M 1600	H-RO MO 2M, H-P MO 202, H-SHK MO R 2, H-T ME 1600	MSE 3M 1600	H-RO MO 3M, H-P MO 202, H-SHK MO R 3, H-T ME 1600
MSE 2M 1800	H-RO MO 2M, H-P MO 202, H-SHK MO R 2, H-T ME 1800	MSE 3M 1800	H-RO MO 3M, H-P MO 202, H-SHK MO R 3, H-T ME 1800